

TIG – PORTIONING MACHINE INTO DISKS



It cuts hard cheeses in halves or in disks. The portioning is made by the engraving of the rind and the cut by amonic steel wire. The shape portioned goes on conveyor belt of loading/unloading.

- through the operator panel it sets:
- height of rind to cut
 - quantity of disks
 - thikness of disks

TECHNICAL DATA

Construction / Stainless Steel Aisi 304/316

Electric supply / 400V 3PH + T 50 Hz

Pneumatic supply / 6 bar

4,5 Kw / **Installed power**

1400 x 1600 x h 1200 mm / **Overall machine dimension**

Production